

SPECTROSPIN NMR Magnet System

SPECTROSPIN NMR Magnet System Trouble Shooting

Version 002

BRUKER

The information in this manual may be altered without notice.

BRUKER accepts no responsibility for actions taken as a result of use of this manual. BRUKER accepts no liability for any mistakes contained in the manual, leading to coincidental damage, whether during installation or operation of the instrument. Unauthorised reproduction of manual contents, without written permission from the publishers, or translation into another language, either in full or in part, is forbidden.

This manual was written by

Jörg Arnold

© 05.12.1996: Spectrospin AG

CH-8117 Fällanden, Switzerland

P/N: Z31408 DWG-Nr: 1119002



7	Trouble Shooting	4
7.1	Trouble shooting during Assembly	4
7.2	Trouble shooting during Cool Down Procedure	6
7.3	Trouble shooting during Charging and Shimming	11
7.4	Trouble shooting during Standard Operation	15
7.5	Trouble shooting during Discharging and Warm up	17
7.6	Trouble shooting of the Anti Vibration Magnet Stand	20



7 Trouble Shooting

7.1 Trouble shooting during Assembly

Problem indicators	Possible reasons	Solutions
Tilt indicators and/or shock watches are broken.	Uncareful transportation or transportation accident.	Contact shipping agent, check the whole magnet system for damages.
Visible damages.	Uncareful transportation.	Contact shipping agent, check all tilt indicators and shock watches.
Ceiling height too low for assembly on magnet stand.		Do the assembly on the assembling feet.
Ceiling height too low for exchange of helium level sensor.		Insert helium level sensor while magnet system is on the assembling feet.
He vessel and N_2 vessel are not concentric.	Alignment is not done cor- rectly.	Repeat the alignment of the He vessel and the N_2 vessel.
	Alignment rod is lose.	Check fixation of the alignment rods.
	Alignment rod is broken.	Replace defective alignment rod.
	Reduction flanges may be non concentric.	Check orientation of the non concentric reduction flange.
N_2 vessel and OVC are not concentric.	Reduction flanges may be non concentric.	Repeat alignment of the N_2 vessel and the OVC.
Vacuum in OVC does not reach 10 ⁻⁵ mbar within 48 hours.	O rings may be leaky	Check vacuum tubing to the vacuum pump. Check O rings in the vacuum valve. Check O rings and sealing surfaces on reduction flanges and on sealing flanges. Check O ring and sealing surfaces of the drop off plate.



Problem indicators	Possible reasons	Solutions
Vacuum in OVC does not reach 10 ⁻⁵ mbar within 48 hours.	Room temperature bore tube has scratches or dust on the sealing surfaces.	Check sealing surfaces on the room temperature bore tube: No scratches and no dust must be visible!
	Moisture may have entered the OVC during transporta- tion or during assembly.	Pump and flush the OVC several times with dry nitro- gen gas to remove moisture.
	Pump stand is defective and does not reach the required vacuum of 10^{-6} mbar.	Check pump stand. Pumping directly against a sealing cap produces pres- sure below 10 ⁻⁶ mbar.
Upper pillar brace collides with vacuum valve.	Vacuum valve is not orienta- tes parallel to the pillar brace.	Turn the vacuum valve until the flange does not collide with the pillar brace any more. This operation may be carefully done with evacua- ted OVC.
Superisolation touches OVC or radiation shield or bore tubes.	Superisolation was not fixed correctly during assembly.	Fix the superisolation on the N_2 vessel properly with the supplied polyester tape. Avoid any connection between different vessels or bore tubes in the cryostat carefully!



7.2 Trouble shooting during Cool Down Procedure

Problem indicators	Possible reasons	Solutions
Precooling with liquid nitro- gen proceeds too slowly.	Transport dewar for liquid nitrogen is empty.	Refill transport dewar.
	Transfer pressure is too low.	Increase transfer pressure.
	Transport dewar is leaky, no transfer pressure may be applied.	Check transport dewar for leakage and seal gas supply tubing.
Precooling with liquid nitro- gen proceeds too fast.	Transfer pressure is too high.	Immediatly stop precooling and adjust transfer pressure properly.
	Large coils must be precoo- led with ACD* (Automatic Cooling Device).	Connect ACD* correctly to the NMR magnet system for cool down procedure.
Vacuum in OVC does not reach 10 ⁻⁶ mbar during pre- cooling.	O rings may be leaky.	Stop precooling and warm up the NMR magnet system. Check vacuum tubing to vacuum pump. Check O rings in the vacuum valve. Check O rings and sealing surfaces on reduction flanges and on sealing flanges. Check O ring and sealing surfaces of the drop off plate.
	O ring is frozen due to con- tact with liquid nitrogen.	Immediatly stop transferring liquid nitrogen. Warm up O ring with warm air! Wait until vacuum recovers and prevent liquid nitrogen from splashing on O rings.
	Pump stand is defective and does not reach the required vacuum of 10^{-6} mbar.	Check pump stand. Pumping directly against a sealing cap produces pres- sure below 10 ⁻⁶ mbar.



Problem indicators	Possible reasons	Solutions
The OVC becomes cold and wet.	Pumping was stopped. Vacuum is broken or worse than 10 ⁻³ mbar.	Do not remove the pumping unit until collection of liquid helium starts in the helium vessel! Find reason of vacuum pro- blem (O ring, pump, frozen O ring) and proceed follo- wing the points mentioned there.
	Cold leak after transportation (transportation damage).	Contact Bruker/Spectrospin for further help.
Room temperature bore tube shows cold spot (condensing or freezing moisture on the bore tube).	Room temperature bore tube and N_2 bore are not aligned correctly and are touching each other.	Stop the cool down proce- dure. Warm up the system and repeat the alignment.
No liquid nitrogen is found when starting to pump back liquid nitrogen after pre- cooing.	The precooling L-tube is not inserted cpmpletly into the syphon.	Insert the L-tube completly into the syphon.
	The precooling L-tube is not tight in the syphon.	Check the lower and of the precooling L-tube for defor- mations and spread it slightly to fit into the syphon.
	No liquid nitrogen is col- lected int he helium vessel.	Check with the dipstick, to be sure that the helium vessel is completly empty of liquid nitrogen and of frozen nitro- gen! (nitrogen ice).
The helium manifold beco- mes very cold and icy during pumping while pumping and flushing.	There is remaining liquid nitrogen in the helium ves- sel, boiling off strongly during pumping.	Stop pumping immediatly and carefully remove all liquid nitrogen through the L-tube. Check with the dipstick to be sure that the helium vessel is completly empty of liquid nitrogen and of frozen nitrogen! (nitrogen ice).



Problem indicators	Possible reasons	Solutions
After some intervals of pum- ping and flushing it is not possible to reach a vacuum in the range of 1 mbar.	The spheres in the quench valves are not sitting cor- rectly in the O rings and thus the quench valves are leaky.	Immediatly stop pumping. Remove frozen air and fro- zen moisture with warm helium gas. Make tight the quench valves by slightly greasing the O rings and checking the position of the spheres. Check with the dipstick to be sure that the helium vessel is completly empty of liquid nitrogen and of frozen nitrogen! (nitrogen ice).
	There is remaining liquid nitrogen in the helium ves- sel, boiling off strongly during pumping.	Stop pumping immediatly and carefully remove all liquid nitrogen through the L-tube. Check with the dipstick to be sure that the helium vessel is completly empty of liquid nitrogen and of frozen nitrogen! (nitrogen ice).
Frozen nitrogen (nitrogen ice) is found in the helium vessel.	Pumping intervals during pumping and flushing were too long and remaining nitro- gen was boiling off and then freezing.	Warm up the magnet coil with warm helium gas through the L-tube and the syphon until the whole coil is warmer than 90° Kelvin. Check the temperature of the coil with the ACD*. Repeat pumping and flushing and carefully check with the dipstick to be sure that the helium vessel is completly empty of liquid nitrogen and of frozen nitrogen! (nitrogen ice).
The transfer of liquid helium does not start.	The transfer pressure in the transport dewar is too low.	Increase the transfer pres- sure.
	The transfer dewar is leaky, there is no transfer pressure built up.	Check transport dewar for leakage. Make all con- nections tight.



Problem indicators	Possible reasons	Solutions
	The transport dewar is empty.	Use new transport dewar.
	The syphon or the helium transfer line are blocked with ice.	Check syphon and transfer line for blockages, remove ice with warm helium gas.
The cool down of the magnet coil does not proceed alt- hough helium is transferred from the transport dewar into the cryostat.	The helium transfer line may be defective.	Check the helium transfer line for icing. If there are cold spots visible, replace the transfer line.
	The extension is not moun- ted on the transfer line. The liquid helium is not forced to flow through the syphon down to the bottom of the helium vessel.	Mount the extension piece on the transfer line. Check the helium transfer line to be inserted completely into the syphon.
The zero reading of the helium level meter can not be adjusted at the beginning of the cool down with liquid helium.	The level sensor is not con- nected properly with the con- nector in the helium manifold.	Check the connection in the helium turret between level sensor and connector.
	The level meter is defective.	Check the level meter with the 0% calibration plug.
The helium level never rea- ches 100% after the cool down.	The transport dewar is empty, no more helium is transferred into the cryostat.	Use new transport dewar.
	The levelsensor is disturbed by the transfer line's exten- sion piece.	Stop transfering helium. Remove the transfer line and measure the helium level after some minutes without transfer line.
	The final filling should not be done through the syphon. The helium in the vessel is disturbed too much.	Use for final filling and for refilling of the cryostat the helium transfer line without extension piece.



Problem indicators	Possible reasons	Solutions
The OVC becomes wet and cold.	Pumping was stopped. Vacuum is broken or worse than 10 ⁻³ mbar.	Do not remove the pumping unit until collection of liquid helium starts in the helium vessel! Find reason of vacuum pro- blem (O ring, pump, frozen O ring) and proceed follo- wing the points mentioned there.
	Cold leak after transporta- tion. (transportation damage)	Contact Bruker/Spectrospin for further help.
Room temperature bore tube shows cold spot (condensing or freezing moisture on the bore tube).	Room temperature bore tube and N_2 bore are not aligned (correctly and are touching each other.	Stop the cool down proce- dure. Warm up the system and repeat the alignment.
After cool down the helium boil off is higher than speci- fied. (up to 5 times)	Normal behaviour. The radiation shields and the insulation need some days to reach final low temperatures.	Wait some days and super- vise helium boil off. The presence of the current lead in the left helium turret during charging and shim- ming helps to cool down the radiation shield.
After cool down the nitrogen boil off is zero.	The nitrogen security flow system has not been mounted correctly during the cool down with helium. Due to supercooling of the nitrogen vessel during cool down with helium, air was sucked into the N_2 vessel and ice is blok- king the N_2 turrets.	Immediatly check the nitro- gen turrets for the presence of ice and remove the ice with warm helium gas!



7.3 Trouble shooting during Charging and Shimming

Problem indicators	Possible reasons	Solutions
The current lead can not be inserted completely into the connector.	The connector is covered with ice. (frozen moisture or frozen nitrogen)	Carefully remove the ice with warm helium gas. To remove little ice spots use the dipstick as tubing for the warm helium gas.
	The shorting plug was not removed after cool down.	Remove the shorting plug with the extraction rod.
	The orientation of the current lead is not correct.	Turn the current lead care- fully until it can be inserted correctly into the connector.
The shim heaters and/or the main heater can not be activated with the cryo power supply.	The current lead is not inser- ted correctly into the con- nector.	Turn the current lead care- fully until it can be inserted correctly into the connector.
	The connector is covered with ice. (frozen moisture or frozen nitrogen)	Carefully remove the ice with warm helium gas. To remove little ice spots use the dipstick as tubing for the warm helium gas.
	The connectors "A" and "B" of the control cable are mis- matched on the current lead's connectors.	Connect the control cable correctly to the current lead. See figures in chapter 3 for details of the current lead.
With closed main heater it is not possible to do the 100 A (120 A) test with the cryo power supply.	The main current cable is not connected properly to the current lead and/or the cryo power supply.	Connect the main current cable correctly to the current lead and the cryo power supply.
	The switch "Main Coil/OFF/Shim Coil" is not put on the "Main Coil" position.	Put the switch on the "Main Coil" position.



Problem indicators	Possible reasons	Solutions
With closed main heater it is not possible to do the 100 A (120 A) test with the cryo power supply.	The main current contacts on the current lead and/or the main current cable are oxida- ted and thus have too high resistance.	Clean main current contacts carefully. Connect current lead and main current cable correctly.
	The cryo power supply and/ or the main current cable are defective.	Check the cryo power supply and the main current cable with a short circuit plug.
The sense voltage can not be set correctly to charge the magnet.	The main heater switch is set to the "OFF" position. The main switch is not opened.	Put the main heater switch to the "ON" position and check the main heater current to be adjusted correctly.
	The main heater current is set too low. The main switch is not opened.	Adjust main heater current correctly. See chapter 3.1 for specified values.
	The auxiliary shorting plug is inserted in the right helium turret and makes a short circuit across the main coil.	Remove the auxiliary shor- ting plug.
	600 MHz systems: The 22 pin shorting plug is inserted in the rear helium turret and makes a short circuit across the main coil.	Remove the 22 pin shorting plug.
The magnet quenches during charging.	Happens sometimes, caused by internal stress during charging.	Repeat cool down with helium within an hour after the quench. Wait the indicated time before charging the magnet again. For details see chapters 3 and 4 in the manual.
	The helium level was too low for charging.	Never try to charge the magnet with less than the minimum allowed level in the helium vessel. See chapter 3 for details.



Problem indicators	Possible reasons	Solutions
The magnet quenches during charging.	The cryo power supply is defective! The main current is oscilla- ting.	Replace cryo power supply.
The main coil switch can not be closed on field.	The helium level is too low for charging. The main coil switch is not covered with liquid helium.	Never try to charge the magnet with less than the minimum allowed level in the helium vessel. See chapter 3 for details.
	The cryo power supply is defective! The main current is oscillating.	Replace cryo power supply.
The shim current can not be set correctly.	The control cable is not con- nected correctly to the cur- rent lead and/or the cryo power supply.	Correctly connect the control cable to the current lead and to the cryo power supply.
	The switch "Main Coil/OFF/ Shim Coil" is not put on the "Shim Coil" position.	Put the switch "Main Coil/ OFF/Shim Coil" on the "Shim Coil" position.
The shim current stops at approximatly 80 mA and can not be set to a higher value	"A" and "B" connectors of the control cable are mismat- ched on the current lead. Caution: The shim current flows through the main hea- ter and will open it!	Immediatly check whether the magnet is in the persi- stent mode anymore. If not, immediatly prepare the main current cable and put hte cryo power supply in the "Main Coil" mode. Recharge the magnet and make it persistent on the cor- rect field!
The shims have no effect on the NMR signal.	The shim heater current is set too low. The shim switches are not opened.	Set the shim heater current to the specified value according to chapter 3.



Problem indicators	Possible reasons	Solutions
The magnet can not be shim- med to reach specifications again.	There is some magnetic material in the room tempe- rature bore tube (bostich, iron chip, rusty dust or simi- lar).	Carefully clean the room temperature bore tube with a wet kleenex. Caution: Magnetic chips will be strongly attracted and will be drawn to the magne- tic center. Try to wrap them up with the kleenex at the end of the bore tube!
	Massiv ferromagnetic parts are in the vincinity of the magnet that are strongly influencing the magnet.	Keep maximum possible distance between magnet and ferromagnetic parts. Repeat cryoshimming, star- ting with the low order shims and the values stated in chap- ter 3.1 of the manual.
The shimming procedure produces irreversible field shift.	Normal behaviour with 600 MHz systems.	Charge the magnet to a gig- her (lower) field as stated in chapter 3. The Z^2 -shift consists of the values of the Z^2 -shim itself and the effects of shimming.



7.4 Trouble shooting during Standard Operation

Problem indicators	Possible reasons	Solutions
The N ₂ boil off falls to zero.	The N ₂ neck tubes are blok- ked with ice.	Remove the heat exchangers and remove the frozen moi- sture. Check the O rings in the heat exchangers and mount them correctly on the N_2 turrets.
	During refill of helium supercooling of the N_2 vessel leads to reduced boil off.	Check some hours after the refill of helium, that there is normal N_2 boil off. Otherwise remove ice as described above.
	The N ₂ vessel is empty.	Immediatly refill the N ₂ ves- sel. Keep a filling record. For specified hold time see chapter 4.
The helium boil off falls to zero.	The atmospheric pressure is increasing.	Normal behaviour, watch helium boil off daily.
	The He neck tubes are blok- ked with ice.	Immediatly call a Bruker/ Spectrospin service engineer. Do not try to remove ice in the helium turrets without special knowledge!
The helium boil off is too high.	The helium level meter is permanently on (service mode) or used frequently.	Measure the helium level once a week or less. Keep a helium level record. Every measuring of the helium level incorporates some helium losses due to the heating of the sensor.
	The atmospheric pressure is decreasing.	Normal behaviour. The Electronic Atmospheric Pressure Device (EAPD) is able to stabilize the pressure in the helium vessel within 0,1 mbar. (optional)



Problem indicators	Possible reasons	Solutions
The helium boil off is too high.	The pressure in the helium vessel is increasing due to blocked helium neck tubes or blocked helium manifold.	Immediatly check helium boil off. If the helium neck tubes are blocked imme- diatly call a Bruker/Spectro- spin service engineer. Do not try to remove ice in the helium turrets without special knowledge!
	The radiation baffles are not inserted in the helium turrets.	Insert the radiation baffles into the left (and rear) helium turret.
	The helium oscillation dam- per is not mounted on the left helium neck tube.	Mount the helium oscilla- tion damper on the left helium neck tube.
The NMR spectrum shows strong vibrations at approxi- mately 43 Hz.	The helium oscillation dam- per is not mounted on the left helium neck tube.	Mount the helium oscilla- tion damper on the left helium neck tube.



7.5 Trouble shooting during Discharging and Warm up

Problem indicators	Possible reasons	Solutions
The shorting plug cannot be removed from its place.	The connectors are covered with ice.	Carefully remove the ice with warm helium gas. To remove little ice spots use the dipstick as tubing for the warm helium gas.
The current lead can not be inserted completely into the connector.	The connector is covered with ice. (frozen moisture or frozen nitrogen)	Carefully remove the ice with warm helium gas. To remove little ice spots use the dipstick as tubing for the warm helium gas.
	The shorting plug was not removed.	Remove the shorting plug with the extraction rod.
	The orientation of the current lead is not correct.	Turn the current lead care- fully until it can be inserted correctly into the connector.
The shim heaters and/or the main heater can not be activated with the cryo power supply.	The current lead is not inser- ted correctly into the con- nector.	Turn the current lead care- fully until it can be inserted correctly into the connector.
	The connector is covered with ice. (frozen moisture or frozen nitrogen)	Carefully remove the ice with warm helium gas. To remove little ice spots use the dipstick as tubing for the warm helium gas.
	The connectors "A" and "B" of the control cable are mis- matched on the current lead's connectors.	Connect the control cable correctly to the current lead. See figures in chapter 3 for details of the current lead.
With closed main heater it is not possible to do the 100 A (120 A) test with the cryo power supply.	The main current cable is not connected properly to the current lead and/or the cryo power supply.	Connect the main current cable correctly to the current lead and the cryo power supply.



Problem indicators	Possible reasons	Solutions
With closed main heater it is not possible to do the 100 A (120 A) test with the cryo power supply.	The switch "Main Coil/OFF/Shim Coil" is not put on the "Main Coil" position.	Put the switch on the "Main Coil" position.
	The main current contacts on the current lead and/or the main current cable are oxida- ted and thus have too high resistance.	Clean main current contacts carefully. Connect current lead and main current cable correctly.
	The cryo power supply and/ or the main current cable are defective.	Check the cryo power supply and the main current cable with a short circuit plug.
The sense voltage can not be set correctly to charge the magnet.	The main heater switch is set to the "OFF" position. The main switch is not opened.	Put the main heater switch to the "ON" position and check the main heater current to be adjusted correctly.
	The main heater current is set too low. The main switch is not opened.	Adjust main heater current correctly. See chapter 3.1 for specified values.
	The auxiliary shorting plug is inserted in the right helium turret and makes a short circuit across the main coil.	Remove the auxiliary shor- ting plug.
	600 MHz systems: The 22 pin shorting plug is inserted in the rear helium turret and makes a short circuit across the main coil.	Remove the 22 pin shorting plug.
The magnet quenches during charging.	The helium level was too low for charging.	Never try to charge the magnet with less than the minimum allowed level in the helium vessel. See chapter 3 for details.
	The cryo power supply is defective! The main current is oscilla- ting.	Replace cryo power supply.



Problem indicators	Possible reasons	Solutions
The shim current can not be set correctly.	The control cable is not con- nected correctly to the cur- rent lead and/or the cryo power supply.	Correctly connect the control cable to the current lead and to the cryo power supply.
	The switch "Main Coil/OFF/ Shim Coil" is not put on the "Shim Coil" position.	Put the switch "Main Coil/ OFF/Shim Coil" on the "Shim Coil" position.
The nitrogen boil off is zero after the discharging of the magnet.	Due to supercooling of nitro- gen air was sucked into the nitrogen vessel and frozen moisture blocks the nitrogen turrets.	Remove the ice from the nitrogen turrets.
After breaking the vacuum with nitrogen with a needle valve, the helium and nitro- gen boil off are very high.	The liquid cryogens have not been removed from the ves- sels before breaking the vacuum.	Blow out the liquid helium with warm helium gas blown through the L-tube into the syphon. Blow out the liquid nitrogen into a transport dewar.
The vacuum is not broken completely after 12 hours.	The vacuum valve has closed itself due to pressure differences.	Block the operator of the vaccum valve with the split plastic tube.
The room temperature bore tube is wet and cold before disassembly of the dewar.	The magnet coil has not yet warmed up completely.	Wait one more day. Never open a dewar before the room temperature bore tube is warm and dry!



7.6 Trouble shooting of the Anti Vibration Magnet Stand

Problem indicators	Possible reasons	Solutions
The anti vibration magnet stand does not reach the ope- rating position.	The air controller is on the "DOWN" position.	Put the air controller to the "UP" position.
	The pressure of the gas supply is too low.	Check the pressure of the gas supply. It must be in the range of 5 bar to 8 bar (70 psi to 112 psi).
	The pneumatic tubings or connectors are leaky.	Check the pneumatic tubings and connectors for leakage.
	The NMR magnet system is not leveled correctly.	Deactivate the anti vibration units or the vibration dam- pers. Check the leveling of the cryostat as described in chapter 6.
	The operating position is not leveled correctly.	Activate the anti vibration units or the vibration dam- pers. Check the leveling of the cryostat as described in chapter 6. Contact a Bruker/Spectro- spin service engineer to repeat the leveling of the NMR magnet system if necessary.
	A level valve is defective.	Contact a Bruker/Spectro- spin service engineer to exchange the devective level valve
	The membrane of a vibration damping unit is defective.	Contact a Bruker/Spectro- spin service engineer to repair or exchange the defec- tive vibration damping unit.
The NMR spectrum shows massive vibrations.	The air controller is on the "DOWN" position.	Put the air controller to the "UP" position.



Problem indicators	Possible reasons	Solutions
	The vibration dampers are pumped to strongly. The damping efficiency is redu- ced.	Check the pressure in the vibration dampers. Adjust the pressure as described in chapter 6.
	The cryostat can not play freely in the operating postion. The dewar has direct mechanical contact with the floor.	Check the leveling of the NMR magnet system with deactivated as well as with activated vibration damping units. With activated vibration damping units no scratching or touching between cryo- stat and magnet stand is observed.
	The dewar has direct mecha- nical contact with the floor.	Check that no direct mecha- nical contact between cryo- stat and floor is produced by any accessory close to the NMR magnet system.

